

T 0 3 3 6 9 " 6 6 0 3 3 6 5 0




FIG. 1




FIG. 2




FIG. 3






FIG. 4



## Insertion Loss Resulting from Angular Alignment of Optical signal



**FIG. 5B**





FIG. 6

FIG. 7









FIG. 8

FIG. 8





FIG. 9




FIG. 10




FIG. 11




FIG. 12